

Clinical Laboratory of San Bernardino, Inc.

Celebrating 50 Years of Analytical Service 1967-2017



Fullerton, City of
303 W. Commonwealth Ave.
Fullerton CA, 92832

Project: School Lead Program
Sub Project: Lead Sampling for FSD / Hermosa Drive Elementary
Project Manager: Don Davenport

Work Order: 18A2613
Received: 01/31/18 14:25
Reported: 02/06/18

3010010-ABE-A 18A2613-01 (Water) Sample Date: 01/31/18 6:11 Sampler: P. Driesler

Analyte	Method	Result	Rep. Limit	Action Level	Units	Prepared	Analyzed	Batch	Qualifier
---------	--------	--------	------------	--------------	-------	----------	----------	-------	-----------

Metals

Lead (Pb) SM3113-B ND 5.0 15 ug/L 02/02/18 02/02/18 1805140

3010010-ABE-B 18A2613-02 (Water) Sample Date: 01/31/18 6:19 Sampler: P. Driesler

Analyte	Method	Result	Rep. Limit	Action Level	Units	Prepared	Analyzed	Batch	Qualifier
---------	--------	--------	------------	--------------	-------	----------	----------	-------	-----------

Metals

Lead (Pb) SM3113-B ND 5.0 15 ug/L 02/02/18 02/02/18 1805140

3010010-ABE-C 18A2613-03 (Water) Sample Date: 01/31/18 6:24 Sampler: P. Driesler

Analyte	Method	Result	Rep. Limit	Action Level	Units	Prepared	Analyzed	Batch	Qualifier
---------	--------	--------	------------	--------------	-------	----------	----------	-------	-----------

Metals

Lead (Pb) SM3113-B ND 5.0 15 ug/L 02/02/18 02/02/18 1805140

3010010-ABE-D 18A2613-04 (Water) Sample Date: 01/31/18 6:30 Sampler: P. Driesler

Analyte	Method	Result	Rep. Limit	Action Level	Units	Prepared	Analyzed	Batch	Qualifier
---------	--------	--------	------------	--------------	-------	----------	----------	-------	-----------

Metals

Lead (Pb) SM3113-B ND 5.0 15 ug/L 02/02/18 02/02/18 1805140

3010010-ABE-E 18A2613-05 (Water) Sample Date: 01/31/18 6:35 Sampler: P. Driesler

Analyte	Method	Result	Rep. Limit	Action Level	Units	Prepared	Analyzed	Batch	Qualifier
---------	--------	--------	------------	--------------	-------	----------	----------	-------	-----------

Metals

Lead (Pb) SM3113-B ND 5.0 15 ug/L 02/02/18 02/02/18 1805140


ND Analyte NOT DETECTED at or above the reporting limit

Stu Styles

Client Services Manager

Clinical Laboratory of San Bernardino, Inc.

EDT Transfer Confirmation 1



Work Order: 18A2613

Report Date: 02/06/2018

Analyzing Lab: Clinical Laboratory of San Bernardino, Inc. ELAP 1088

CITY OF FULLERTON		User ID: TFE	System: 3010010
Hermosa Drive Elemen-Partition 4 Bubbler	Station No.: 3010010-ABE-A	Sampled: 180131 06:11	
LEAD	Result: ND	Units: UG/L	Entry No.: 01051 Analyzed: 180202
Hermosa Drive Elemen-Partition 3 Drinkin	Station No.: 3010010-ABE-B	Sampled: 180131 06:19	
LEAD	Result: ND	Units: UG/L	Entry No.: 01051 Analyzed: 180202
Hermosa Drive Elemen-Partition 3 Bubbler	Station No.: 3010010-ABE-C	Sampled: 180131 06:24	
LEAD	Result: ND	Units: UG/L	Entry No.: 01051 Analyzed: 180202
Hermosa Drive Elemen-Partition 2 Drinkin	Station No.: 3010010-ABE-D	Sampled: 180131 06:30	
LEAD	Result: ND	Units: UG/L	Entry No.: 01051 Analyzed: 180202
Hermosa Drive Elemen-Partition 5 Drinkin	Station No.: 3010010-ABE-E	Sampled: 180131 06:35	
LEAD	Result: ND	Units: UG/L	Entry No.: 01051 Analyzed: 180202

